


## DND-AC M5 F PANTHER

### Magnetic induction

Distance (mm)*	Magnetic induction (Gauss)**
0 mm	2230
50 mm	1520
100 mm	953
150 mm	635
200 mm	454
250 mm	326
300 mm	250
350 mm	188
400 mm	145

### Magnetic induction (Gauss chart) - DND-AC M5 F PANTHER



\* \*Measured from the separator belt to the conveyor belt

\*\* Testing without material loading

\*\*\* Measurement axis - in the center of the magnetic core

Magnetic tolerance: +/- 10 %