


## DND-AC M1 F PANTHER

### Magnetic induction

| Distance (mm)* | Magnetic induction (Gauss)** |
|----------------|------------------------------|
| 0 mm           | 2230                         |
| 50 mm          | 993                          |
| 100 mm         | 882                          |
| 150 mm         | 401                          |
| 200 mm         | 295                          |
| 250 mm         | 201                          |
| 300 mm         | 133                          |
| 350 mm         | 115                          |
| 400 mm         | 92                           |

### Magnetic induction (Gauss chart) - DND-AC M1 F PANTHER



\* \*Measured from the separator belt to the conveyor belt

\*\* Testing without material loading

\*\*\* Measurement axis - in the center of the magnetic core

Magnetic tolerance: +/- 10 %