


DND-AC M2 F PANTHER

Magnetic induction

Distance (mm)*	Magnetic induction (Gauss)***
0 mm	2230
50 mm	1330
100 mm	892
150 mm	514
200 mm	379
250 mm	298
300 mm	219
350 mm	175
400 mm	114

Magnetic induction (Gauss chart) - DND-AC M2 F PANTHER



* * Measured from the separator belt to the conveyor belt

** Testing without material loading

*** Measurement axis - in the center of the magnetic core

Magnetic tolerance: +/- 10 %