


DND-AC M3 F PANTHER

Magnetic induction

Distance (mm)*	Magnetic induction (Gauss)**
0 mm	2230
50 mm	1520
100 mm	953
150 mm	635
200 mm	454
250 mm	326
300 mm	250
350 mm	188
400 mm	145

Magnetic induction (Gauss chart) - DND-AC M3 F PANTHER



* * Measured from the separator belt to the conveyor belt

** Testing without material loading

*** Measurement axis - in the center of the magnetic core

Magnetic tolerance: +/- 10 %