


## DND-AC N7 JACKAL

### Magnetic induction

Distance (mm)*	Magnetic induction (Gauss)***
0 mm	2700
50 mm	1731
100 mm	1057
150 mm	664
200 mm	455
250 mm	307
300 mm	264
350 mm	164
400 mm	115

### Magnetic induction (Gauss chart) - DND-AC N7 JACKAL



\* \*Measured from the separator belt to the conveyor belt

\*\* Testing without material loading

\*\*\* Measurement axis - in the center of the magnetic core

Magnetic tolerance: +/- 10 %